



# J21 Process Area Map



N  
1ST FLOOR PLAN  
PROCESS AREA



N  
2ND FLOOR PLAN  
PROCESS AREA

## MDB PROCESS AREA MAP

THE CROSS HATCHED AREA IS WITHIN THE  
MDB TOXIC AREA. NO EQUIPMENT MATERIAL  
OR DEBRIS MAY BE SALVAGED OR RECYCLED  
FROM THIS AREA.